

Test Report No. SL119012702145TX

Date: Aug 13, 2019

Page 1 of 2

BEIJING EMBFAN TECH. LIMITED

ROOM 633, ZHONG TENG JIAN HUA BUSINESS BUILDING, NO.64 JIAN CAI CITY ROAD HUI LONG GUAN TOWN CHANG PING DISTRICT BEIJING CITY PRC

The following sample(s) was/were submitted and identified on behalf of the client as:

(A) Knitted pants: 100%polyester in black
(B) Knitted fabric: 100%polyester in yellow
BEIJING EMBFAN TECH. LIMITED
ROOM 633, ZHONG TENG JIAN HUA BUSINESS BUILDING, NO.64 JIAN
CAI CITY ROAD HUI LONG GUAN TOWN CHANG PING DISTRICT BEIJING CITY PRC

Manufacturer Country of Destination	:	China Australia		
Test Performed	ŝ	Selected test(s) as requested by applicant		
Sample Receiving Date Testing Period Test Result(s)	с. С.	Aug 08, 2019 Aug 08, 2019 - Aug 13, 2019 Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. For further details, please refer to the following page(s).		

Signed for and on behalf of SGS-CSTC Standards Technical Service (Tianjin) Co., Ltd

And wei

Shepherd Wei (Account Executive)



Unless athenesise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overless, available on regulated or accessible at http://www.sqs.com/an.Terms.and.com/documents. available to Terms and Conditions for Electronic Documents at http://www.sqs.com/an.Terms.and.com/documents. Attention is down to the instruction of labeling, indemnification and print field the sub-conditions of the company sub-conditions of the company is a set of the company in the set of the company is a set responsibility in the company's field the set of the company is a set of the company's field the set of the company is a set responsibility in the company's field the set of the document is the set of the company's set responsibility is to be responsibility in the company's field the

SGS Mansion, No.41, The 5th Avenue TEDA, Tianjin, China: 300457 1 (86-22) 55288414 1 (86-22) 25282879 www.sgsgroep.com.on 中國 - 天语古協派杜术开发应第五大条41号SGS大量 邮编: 300457 1 (86-22) 55288414 1 (86-22) 25283879 年 sgs.china@sgs.com



Test Report

No. SL119012702145TX

Test Result

Pilling Resistance

(ISO 12945-2:2000; Martindale Abrasion & Pilling Tester, Total Load Applied 155g.)

As received After 2000 rubs	<u>(A)</u>	<u>(B)</u>
Rating	4-5	4-5

Remarks: Pilling Rating

- 5 No change
- 4 Slight surface fuzzing and/or partially formed pills
- 3 Moderate surface fuzzing and/or moderate pilling. Pills of varying size and density partially covering the specimen
- 2 Distinct fuzzing and/or distinct pilling. Pills of varying size and density covering a large proportion of the specimen surface
- 1 Dense surface and/or severe pilling. Pills of varying size and density covering the whole of the specimen surface



*** End of Report ***



Meas otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed writing and the company of the accessible at high (areas sign commit) from and conditions areas and, for electronic formal documents, subject to Terms and Conditions for Electronic Documents of high (areas sign commit) forms and conditions of Service printed to the sign of the sign of the sign of the sign of the company subject to the sign of the sign of

SGS Mansion, No.41, The S^a Avenue TEDA, Tianjin, China 300457 1 (86-22) 55288414 1 (86-22) 5528879 www.spagroup.com.cn 中國 - 天津古旨济社术开发区第五大条41号SGS大量 邮稿: 300457 1 (86-22) 55288414 1 (86-22) 25293879 * sps.china@sps.com